OMB Control No.: 2127-0004

# **Part 573 Safety Recall Report**

# 15V-345

**Manufacturer Name:** Mazda North American Operations

**Submission Date :** JUN 04,2015 **NHTSA Recall No. :** 15V-345 **Manufacturer Recall No. :** 8215F



#### **Manufacturer Information:**

Manufacturer Name: Mazda North American Operations

Address: 1025 Connecticut Avenue, NW

Suite 910 Washington DC 20036

Company phone: 248-295-7859

## **Population:**

Number of potentially involved: 444,907 Estimated percentage with defect: 0

#### **Vehicle Information:**

Vehicle: 2003-2008 Mazda Mazda6 Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information: Plant information; Auto Alliance International, Inc. Flat Rock, Michigan

Production Dates: MAY 29, 2002 - MAY 05, 2008

### **VIN (Vehicle Identification Number) Range**

Begin: 1YVFP80C735M00220	End: 1YVFP80C935M56997	☐ Not sequential VINs
Begin: 1YVFP80D935M00227	End: 1YVFP80D435M57077	☐ Not sequential VINs
Begin: 1YVFP80CX45N01219	End: 1YVFP80C245N99310	☐ Not sequential VINs
Begin: 1YVFP80D445N04304	End: 1YVFP80D545N99312	☐ Not sequential VINs
Begin: 1YVFP80C255M00001	End: 1YVFP80C355M76942	☐ Not sequential VINs
Begin: 1YVFP84D355M00043	End: 1YVFP82D355M00045	☐ Not sequential VINs
Begin: 1YVFP80C965M00028	End: 1YVFP80C465M71248	☐ Not sequential VINs
Begin: 1YVHP81C335M00030	End: 1YVHP80C835M54604	☐ Not sequential VINs
Begin: 1YVHP80D935M00270	End: 1YVHP80D735M55980	☐ Not sequential VINs
Begin: 1YVHP84C445N05088	End: 1YVHP80C145N99307	☐ Not sequential VINs
Begin: 1YVHP84D045N05095	End: 1YVHP80D745N99286	☐ Not sequential VINs
Begin: 1YVHP84C355M00009	End: 1YVHP80C555M77535	☐ Not sequential VINs
Begin: 1YVHP80D255M00002	End: 1YVHP84D255M77480	☐ Not sequential VINs
Begin: 1YVHP80CX65M00001	End: 1YVHP84C265M71493	☐ Not sequential VINs
Begin: 1YVHP82D465M00002	End: 1YVHP84D065M71498	☐ Not sequential VINs

Description of the Cause: Based upon Takata's investigation to date, the potential for such ruptures may occur

in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity. In addition, this potential for rupturing may

also depend on other factors, including manufacturing variability. Identification of Any Warning that can Occur : NR

### **Supplier Identification:**

# **Component Manufacturer**

Name: Takata/TK Holdings

Address: 12-31 Akasaka 2-chome Minato-ku, Tokyo.

888 16th street, NW, Suite 800 Washingto

**Country: United States** 

## **Chronology:**

On May 18, 2015; Takata signed a Consent Order with NHTSA and submitted DIR, 15E-040, to NHTSA on PSDI-4 frontal driver side airbag inflators.

On May 26, 2015; Mazda and Takata had a conference. Takata explained the 15E-040 in detail, which is related to PSDI-4 installed on 2003-2008MY Mazda6, 2004-2008MY RX-8 and 2006-2007MY Mazdaspeed6.

On June 2, 2015; Mazda had a Quality Audit Committee and determined to conduct a safety recall campaign on 2003-2008MY Mazda6, 2004-2008MY RX-8 and 2006-2007MY Mazdaspeed6 equipped with PSDI-4 frontal driver side airbag inflators during the entire production period.

## **Description of Remedy:**

 $Description \ of \ Remedy \ Program: Owners \ of \ record \ will \ be \ notified \ of \ this \ issue \ and \ instructed \ to \ take \ their$ 

vehicles to a Mazda dealer for repair. The dealer will replace the frontal driver side airbag inflator. The repair will be performed free of charge to the

vehicle owners.

How Remedy Component Differs from Recalled Component: NR

Identify How/When Recall Condition was Corrected in Production: NR

#### **Recall Schedule:**

Description of Recall Schedule: Planned Dealer Notification Date; TBD

Planned Owner Notification Date: TBD

Planned Dealer Notification Date: NR - NR

Planned Owner Notification Date: NR - NR

Part 573 Safety Recall Report	15V-345	Page 4
* NR - Not Reported		
The information contained in this rep	port was submitted pursuant to 49 CFR §573	